




Don't miss out on jobs requiring .025" copper wall tubing!



Many installations fail to comply with recommended water treatment or water velocities, resulting in coil failures. Increasing the tube wall thickness on hydronic coils could prolong the lifespan of a fan coil unit.

Fan Coil .025" Wall Tubing Option

- .025" copper tube wall thickness
- Addresses specification requirement
- Available on all IEC products with 1/2" tube coils*
- Available with Special Feature Request (SFR) only

Reference our [Sales Brochure](#) for specific product availability and lead time information

[Learn More](#)

Submit your Special Feature Request for .025" coil tube through EnCompass for Pricing and Lead Times!